

Номер точки	X	У
3183	393806.75	2142816.05
3184	393791.27	2142819.49
3185	393780.40	2142837.22
3186	393770.10	2142857.24
3187	393763.80	2142868.68
3188	393752.95	2142891.58
3189	393743.20	2142911.61
3190	393745.50	2142924.17
3191	393742.62	2142931.04
3192	393734.05	2142948.19
3193	393738.05	2142957.92
3194	393738.05	2142964.79
3195	393744.90	2142971.09
3196	393751.21	2142983.10
3197	393752.35	2142996.83
3198	393752.36	2143012.87
3199	393750.08	2143034.02
3200	393756.95	2143054.04
3201	393755.80	2143076.35
3202	393755.20	2143098.66
3203	393758.85	2143134.31
3204	393758.25	2143151.47
3205	393755.40	2143170.35
3206	393750.27	2143177.78
3207	393738.21	2143182.70
3208	393730.80	2143190.94
3209	393718.20	2143209.83
3210	393713.05	2143228.70
3211	393713.05	2143241.86
3212	393716.50	2143248.15
3213	393719.35	2143251.01
3214	393717.05	2143281.91
3215	393717.65	2143292.22
3216	393727.35	2143298.50
3217	393733.65	2143311.65
3218	393737.65	2143331.69
3219	393739.40	2143358.58
3220	393733.10	2143383.18
3221	393711.90	2143408.34
3222	393709.06	2143425.49
3223	393691.30	2143438.07
3224	393675.30	2143452.96
3225	393663.85	2143471.84
3226	393633.50	2143497.02
3227	393630.05	2143506.74
3228	393594.59	2143521.61
3229	393578.55	2143534.20
3230	393557.95	2143544.50
3231	393504.30	2143524.47
3232	393495.75	2143516.46

Номер точки	X	У
3233	393477.40	2143515.89
3234	393439.05	2143519.32
3235	393401.30	2143518.76
3236	393377.85	2143512.47
3237	393374.43	2143489.57
3238	393385.85	2143462.68
3239	393387.55	2143427.22
3240	393408.15	2143384.31
3241	393405.30	2143371.72
3242	393329.50	2143415.33
3243	393305.90	2143423.04
3244	393268.20	2143396.30
3245	393246.30	2143402.38
3246	393200.10	2143412.11
3247	393123.50	2143415.75
3248	393052.35	2143415.68
3249	393000.05	2143402.31
3250	392951.40	2143424.19
3251	392893.05	2143408.39
3252	392812.80	2143382.34
3253	392738.60	2143412.04
3254	392739.80	2143432.70
3255	392750.75	2143478.88
3256	392733.75	2143542.10
3257	392716.73	2143589.52
3258	392710.65	2143628.41
3259	392724.00	2143663.66
3260	392726.45	2143692.83
3261	392764.15	2143731.74
3262	392794.55	2143779.14
3263	392792.10	2143818.04
3264	392760.50	2143860.58
3265	392719.15	2143866.67
3266	392642.55	2143844.78
3267	392586.60	2143803.45
3268	392553.80	2143742.67
3269	392544.05	2143638.14
3270	392517.90	2143596.97
3271	392469.25	2143507.01
3272	392207.80	2143400.05
3273	392205.40	2143282.14
3274	392119.05	2143171.53
3275	392135.30	2143146.83
3276	392115.90	2143122.64
3277	392539.86	2142515.09
3278	392419.75	2142462.06
3279	392310.30	2142339.29
3280	392253.15	2142210.42
3281	392273.85	2142136.30
3282	392264.10	2142099.82

Номер точки	X	У
3283	392214.25	2142073.08
3284	392211.85	2142053.62
3285	392039.65	2142117.46
3286	391944.00	2141912.94
3287	391788.98	2141893.15
3288	391608.04	2141860.53
3289	391211.52	2141798.64
3290	390255.80	2142506.97
3291	389817.55	2142828.55
3292	389428.45	2143149.47
3293	388980.80	2143493.30
3294	388973.73	2143485.87
3295	388932.18	2143519.09
3296	388883.27	2143471.46
3297	388894.50	2143448.15
3298	388917.21	2143426.38
3299	388914.73	2143423.77
3300	388890.85	2143443.26
3301	388879.31	2143468.13
3302	388781.49	2143382.34
3303	388777.62	2143378.94
3304	388788.24	2143377.07
3305	388817.82	2143354.01
3306	388839.50	2143344.60
3307	388869.70	2143318.98
3308	388865.65	2143280.06
3309	388887.15	2143249.28
3310	388892.95	2143213.85
3311	388916.75	2143173.19
3312	388935.95	2143165.05
3313	388944.10	2143156.92
3314	388963.24	2143150.53
3315	388986.50	2143130.78
3316	388997.55	2143104.64
3317	388999.30	2143088.37
3318	389012.05	2143084.30
3319	389033.55	2143082.56
3320	389043.30	2143072.22
3321	389039.20	2143058.85
3322	389036.30	2143050.71
3323	389044.45	2143032.71
3324	389062.43	2143011.22
3325	389070.62	2143007.73
3326	389074.65	2142996.10
3327	389071.75	2142987.99
3328	389058.40	2142981.59
3329	389057.25	2142969.39
3330	389072.90	2142946.15
3331	389082.20	2142935.12
3332	389102.55	2142924.09

Номер точки	X	У
3333	389114.75	2142910.15
3334	389122.90	2142913.02
3335	389126.40	2142919.43
3336	389157.75	2142909.56
3337	389171.10	2142898.52
3338	389169.40	2142870.64
3339	389170.55	2142832.87
3340	389177.50	2142809.06
3341	389138.60	2142874.33
3342	389139.15	2142726.00
3343	389144.95	2142688.82
3344	389148.45	2142649.32
3345	389129.85	2142619.69
3346	389099.65	2142610.38
3347	389045.05	2142563.35
3348	389025.25	2142544.74
3349	388993.30	2142491.31
3350	388976.45	2142487.25
3351	388972.36	2142469.81
3352	388959.60	2142448.34
3353	388960.75	2142437.87
3354	388976.45	2142432.06
3355	388982.25	2142423.35
3356	388979.95	2142414.07
3357	388971.80	2142408.85
3358	388966.72	2142405.10
3359	388966.60	2142366.42
3360	388961.11	2142328.60
3361	388943.90	2142289.19
3362	388931.71	2142297.30
3363	388927.05	2142313.56
3364	388925.92	2142337.38
3365	388915.45	2142348.44
3366	388895.10	2142290.33
3367	388866.65	2142215.40
3368	388846.90	2142163.11
3369	388825.38	2142096.32
3370	388799.80	2142060.30
3371	388738.80	2142036.49
3372	388669.65	2142014.41
3373	388630.70	2141983.64
3374	388540.15	2141871.71
3375	388510.40	2141752.80
3376	388551.30	2141626.44
3377	388502.91	2141459.21
3378	388423.05	2141410.90
3379	388411.91	2141344.00
3380	388523.40	2141223.23
3381	388512.25	2141128.46
3382	388545.69	2140981.67

Номер точки	X	У
3383	388674.17	2140969.67
3384	388678.33	2140969.28
3385	389184.05	2140922.01
3386	389174.07	2140817.71
3387	389176.75	2140661.58
3388	389176.84	2140656.48
3389	389139.27	2140425.16
3390	389131.88	2140257.82
3391	389124.86	2140131.22
3392	389369.43	2140023.12
3393	389807.70	2140225.52
3394	389944.32	2140297.30
3395	390000.68	2140014.42
3396	389753.15	2139747.58
3397	389668.82	2139471.13
3398	389153.47	2138985.51
3399	388976.80	2138727.69
3400	388825.38	2138499.42
3401	388808.56	2138413.17
3402	388803.33	2138106.36
3403	388795.36	2137883.89
3404	388749.37	2137735.07
3405	388704.33	2137653.53
3406	388707.61	2137582.38
3407	388670.71	2137501.20
3408	388655.43	2137139.78
3409	388542.24	2137081.55
3410	388530.50	2137052.08
3411	388847.97	2136836.92
3412	388880.73	2136751.02
УТ 49 (3413)	388943.20	2136549.90
3414	389474.69	2136642.99
3415	389548.95	2136663.84
3416	389605.65	2136784.05
3417	389791.21	2137177.43
3418	389816.76	2137231.57
3419	390107.20	2137441.25
3420	390424.07	2137337.03
3421	390548.67	2137296.05
3422	390852.60	2137196.07
УТ 46 (3423)	391155.78	2137282.19
3424	391185.47	2137278.19
3425	391217.06	2137280.41
3426	391464.64	2137429.07
3427	391469.67	2137432.09
3428	391485.82	2137441.79
3429	391572.21	2137617.75
3430	391607.13	2137759.18
3431	391867.52	2137876.14
3432	391936.00	2137924.64

Номер точки	X	У
3433	392022.50	2138040.37
3434	392096.24	2138114.83
3435	392146.87	2138163.41
3436	392160.26	2138181.89
3437	392164.90	2138181.51
3438	392149.76	2138160.65
3439	392096.40	2138103.42
3440	392214.38	2138184.76
3441	392285.28	2138171.75
3442	392289.63	2138171.40
3443	392393.52	2138162.98
3444	392440.52	2138149.54
3445	392452.64	2138161.60
3446	392455.37	2138127.56
3447	392512.62	2138042.84
3448	392524.83	2138021.63
3449	392526.86	2138018.11
3450	392574.18	2137935.97
3451	392575.00	2137934.54
3452	392581.23	2137923.73
3453	392652.58	2137833.29
3454	392557.45	2137209.48
3455	392361.88	2136951.89
3456</		